

M-1068

DATE January 13, 1960

SUBJECTComplementing Checkerboard<br/>ProgramTOPDP Distribution ListFROMJohn C. Conley

This is a utility program for checking the performance and reliability of the magnetic core memory. It works the memory in the roughest way possible and is self-checking for easy location of faulty or weak cores.

The memory is loaded in a fixed order from the test word, using both the test word and its complement.

The content of each register is then checked, and if correct the content is complemented and stored. The program after initial loading is in a continuous loop of checking, complementing, storing and then checking again, complementing and storing. This will continue indefinitely until the machine is stopped manually or on the location of an error during checking.

The memory plane is loaded in the following order, assuming that the test word is all 1's and that the skip instruction in register 1717 is skip on AC positive. This instruction is set by the program and may be a skip on either positive or negative. If negative the load-ing will be the complement of that shown. Any combination of 1's and o's may be used in the test word.

## MEMORY PLANE

Register	0	1	2	3	4	5	6	7	10	11	12	13	14	15	16	17	20	 35	36	37
0	1	0	0	1	1	0	0	1	1	0	0	l	l	0	0	1	1	 0	0	1
40	0	1	1	0	0	1	l	0	0	1	l	0	0	1	1	0	0	 l	1	0
100	l	0	0	1	l	0	0	1	1	0	0	l	l	0	0	l	1			
•	•	٠																		
•	•																			
•	•	-																		
•	٠	٠																		
1640	0	l																		
1700) 1740)			]	Pro	ogi	ran	n :	is	in	the	ese	re	gist	ters	3					

Subject: Complementing Checkerboard Program

## OPERATING INSTRUCTIONS

- 1. Set Test Word to configuration of 1's and 0's you want to use.
- 2. Set Test Address to 1700.
- 3. Push start switch on console.
- 4. The machine will halt at 1745 (PC = 1746) if an error is detected. The AC will show the address of the register containing the error.
- 5. To locate faulty core, set Test Address to address shown in AC. Push examine switch and locate, core which is incorrect. For example, if 1's and 0's have been loaded, faulty core will have a 1 while the rest of the register shows 0's or just the reverse of this.
- 6. To determine what should be in any register examine program registers 1717 and 1737. If they are the same memory should contain what was loaded initially, if they are different the program is in the complement cycle and the complement of what was loaded should be in memory.
  - NOTE: If this examination is made after a halt at 1745, all registers before the address shown in the AC will have been complemented and so be the reverse of the statement above. Those registers after the address in the AC will be as explained above.

Subject: Complementing Checkerboard Program

## COMPLEMENTING CHECKERBOARD

2

Key	Address	Instruction	Code	Comments
	1700 1701 1702	LAC L DAC D DAC G	20 <b>-</b> 1767) 24 <b>-</b> 1737) 24-1717)	Sets skip instruction for initial load and check of memory registers 0-1677
	1703 1704	LAC T DAC F	20-1777) 24-1716)	Puts in dummy instruction for initial loading of memory
Ε	1705 1706	LAC Z DAC Q	20-1772) 24-1775)	Designates first register to be loaded or checked
A	1707 1710 1711 1712 1713 1714 1715	LAC Q RAR 5 XOR Q DAC M RAR 1 XOR M RAR 1	20-1775) 67-1037) 06-1775) 24-1770) 67-1001) 06-1770) 67-1001)	Determines what should be in each memory register
F	1716	(Dummy (JMP D	76-000 60-1737	
L J C B	1717 1720 1721 1722 1723 1724 1725	(SPA SNA LAT JMP B LAT & CMA DAC* Q IDX Q	64) 60-1723) 76-2200) 60-1724) 76-3200) 25-1775) 44-1775)	Loads memory initially
	1726	SAS V	52 <b>-</b> 1771	Checks for last register
	1727	JMP A	60-1707	
	1730	LAC R	20-1774	
	1731	DAC F	24-1716	
	1732 1733 1734 1735	LAT DAC W CMA DAC P	76-2200) 24-1776) 76-1000) 24-1773)	Sets constants from TW for checking
	1736	JMP E	60-1705	Start checking
D	1737	(SPA (SNA	64-0200 64-0400	

Subject: Complementing Checkerboard Program

•

L

ey	Address	Instruction	Code	Comments
N H J	1740 1741 1742 1743 1744 1745 1746 1747 1750 1751 1752	JMP H LAC*Q SAD W JMP J LAC Q Halt LAC*Q SAS P JMP N CMA DAC*Q	60-1746) 21-1775) 50-1776) 60-1751) 20-1775) 76-0400) 21-1775) 52-1773) 60-1744) 76-1000) 25-1775)	Checks memory register and reloads complement. If error is detected halts at 1745 with address of incor rect register in AC
	1753 1754	IDX Q SAS V	Щ <b>-</b> 1775) 52 <b>-</b> 1771)	Checks for last register
	1755	JMP A	60-1707	
	1756 1757 1760 1761 1762 1763 1764	LAC K DAC D DAC M LAC L DAC K LAC M DAC L	20-1766) 24-1737) 24-1770) 20-1767) 24-1766) 20-1770) 24-1767)	Changes skip instruction after each complete run through of memory for next check and complement cycle
	1765	JMP E	60-1705	
Χ	1766	SPA	64-0200	
G	1767	SNA	64-0400	
M	1770			
J	1771		001700	
Z	1772		000000	
Р	1773			
.7	1774		60-1737	
Ĵ	1775			
Ŋ	1776			
	1777		76-0000	

Complementing Checkerboard .. contid.